

# FLORENCE MILL PRODUCTS

532 FLORENCE RD.  
P.O. BOX 15  
FLORENCE, ON N0P 1R0  
CANADA

---

Phone (519) 692-4711  
Fax (519) 692-4711

September 9, 1998

[REDACTED]

[REDACTED]

We have recently started using IXL in our vehicles, one of which is a GMC Astro van that we use for hardware pickups and deliveries. It has over 400,000 km on it. We decided to replace the oil pump on our mechanics recommendation, since it ran exceptionally well but the oil pressure was dropping.

After replacing the oil pump it went on a 600 km pickup and delivery. The oil pressure dropped to 0 after approximately 100 km. Thinking it was the gauge or sensor since the engine was running fine we didn't check the problem until it had 1000km on it. To our shock it had no oil pressure. The new oil pump was defective. Needless to say if it hadn't been for the IXL additive we would have had to replace the engine or the vehicle.

This product has more than paid for itself faster than any other product we have ever used.

Sincerely,

FM Rona Hardware  
Jeff R. [REDACTED] owner

[REDACTED]